

Fume Hood Report

from 08/01/09 to 11/07/09

Date Entered	WO Number	Work Order Description	Action Code	WO Status	Asset Number	LAST NAME
8/13/2009	09-027722-000	CONTE, 162, FUME HOOD AIR FLOW TOO HIGH(139FPM) PLEASE ADJUST AIR FLOW. THANKS, REQ.YUNG MORGAN, Phone: 545-5118 iNET	Routine Service Call	Closed	BU0614-100	HUSTED
8/17/2009	09-028348-000	HASBROUCK LABORATORY ROOM 314 FUME HOOD NOT WORKING PHONED IN JIMMYWARREN REQ.LAURIE GOLDNER WEEKEND LOG SHEET 8/15/09	Dispatch Service Call	Closed	BU0124-100	LEE
8/17/2009	09-028399-000	MORRILL 4 NORTH, 417N, FUME HOOD BLOWER NOT WORKING. MOTOR & FAN MAY BE DAMAGED. REQ:PETER DAWSON@5-5936 iNET	Routine Service Call	Ready	BU0347-100	TOWNSEND
8/19/2009	09-029075-000	LEDERLE GRADUATE CENTER A - RM 1512, DOOR ON FUMEHOOD WILL NOT CLOSE FULLY. PLEASE CHECK AND REPAIR AS NEEDED. REQ:KEFAR JAHAN@50373 RITB034869	Routine Service Call	Closed	FH04121515	TOWNSEND
8/21/2009	09-029197-000	MARCUS HALL, ROOM #7 (LAMMDA LAB COMPLEX), ** Custodial Support ** ECE DEPT REQUEST FOR MEETING, DESIGN REVIEW, & COST ESTIMATE, TO "RE-FURBISH" LAB SPACE, TO INCLUDE THE FOLLOWING: REMOVAL OF SMALL SINK IN NORTHEAST ROOM, CAP PIPING, AND REPAIR WALL, REMOVE FUME HOOD AT ENTRANCE OF ROOM #7, (NORTHWEST CORNER), CAP DUCT, PLUMBING, ECT, AND REPAIR WALL, REMOVE (1) FUME HOOD, (1) SMALL SINK, IN (SOUTHWEST CORNER, CAP DUCT, PLUMBING, ECT, AND REPAIR WALL, REMOVE (1) LARGE STAINLESS STEEL SINK & REPLACE WITH (1) SMALL SINK, AS SELECTED BY PROFESSOR JACKSON, "UP-DATE" AC SYSTEM, AND REMOVE EXISTING AC SYSTEM, (NOTE: UTILIZATION OF EXISTING CHILLED WATER LINES SHOULD BE CONSIDERED), REMOVE CEILING RAIL & PAINT CEILING, REMOVE LARGE STEEL DOORS & REPLACE WITH CONVENTIONAL DOUBLE DOORS, PAINT ALL WALLS, THIS PROJECT MAY INVOLVE MOVING SOME TABLES, FURNISHINGS, (TO BE IDENTIFIED), OUT, DURING PROJECT. THANK-YOU... MADELENE ETKIN, ECE DEPT, IS REQUESTOR FOR THIS REVIEW & ESTIMATE, AT 5-4569, FAX 5-4611 ELAB II, 208, AT THE NORTH END OF LAB 208 THERE IS A SMALL WATER LEAK. WATER IS DRIPPING FROM THE INCOMING TEMPERED WATER LINE DIRECTLY ABOVE FUME HOOD #FH0657-208. (TO THE RIGHT AS YOU ENTER THE MAIN DOOR INTO THE LAB). IF YOU CAN NOT FIND THE PROBLEM EITHER ASK ONE OF THE STUDENTS IN THIS LAB OR ME. THANKS, SHERRIE W-Y ELAB II, 210B REQ.SHERRIE WEBB-YAGODZINSKI, Phone: 577-3231 iNET	Planned Work	Closed	BU0343-000	HAMELIN
8/24/2009	09-029936-000	GRC , 16TH FLOOR INSTALL SURGE PROTECTION FOR COMPUTER BOARDS FOR FUME HOOD FANS. REQ. RAY SAMSON @ 5-6416	Routine Service Call	Closed	BU0657-300	LEE
8/27/2009	09-030327-000	MORRILL 2, 418, FH0127-15 FUME HOOD MAKING LOUD NOISE AND HAD TO BE TURNED OFF. PLEASE CHECK AND REPAIR AS NEEDED.	Routine Service Call	Closed	BU0412-200	HAMELIN
9/4/2009	09-021221-001	MORRILL 4N, 410, ONE OF THE LIGHTS IN THE FUME HOOD IS VERY DIM AND BURNING OUT, PLEASE REPLACE. REQ:JOY WARD@545-9469 iNET	Routine Service Call	Closed	BU0127-110	SAMSON
9/17/2009	09-032966-000	MORRILL SCIENCE CENTER 4 - RM S364, AIR FLOW FOR THIS FUMEHOOD IS TOO HIGH. R-608@10:20 REQ:S.IVES@60449 RITB036028	Routine Service Call	Closed	BU0347-200	TOWNSEND
9/30/2009	09-034628-000	LEDERLE GRADUATE CENTER ROOM 1415--FUME HOOD ON RIGHT HAS A WATER LEAK. PLEASE CHECK. REQ.MARVIN@5-3063 RITB036239	Dispatch Service Call	Ready	FH0347-33S	TOWNSEND
10/5/2009	09-034839-000	MORRILL 3, 401H & 403, LIGHT BULBS BURNT OUT IN FUME HOODS IN BOTH ROOMS LISTED. PLEASE REPLACE LIGHT BULBS. FOR DETAILS SEE MIKE KEEDY (5-3159) OR SALLY IVES (5-0449), REQ.SARA C. IVES, Phone: 5-0449 iNET	Routine Service Call	Closed	BU0412-100	HUSTED
10/7/2009	09-035505-000	POLYMER RESEARCH CENTER, FUME HOOD IN ROOM 262 LOW FLOW. #564 REQ.DAN@5-8232 RITB036308	Routine Service Call	Progressing	BU0290-200	HUSTED
10/8/2009	09-035587-000	POLYMER RESEARCH CENTER, LABORATORY 465B, FUME HOODS EX-84-2 & EX-82-1, BOTH FUME HOODS HAVE FUME HOOD LIGHTS THAT ARE BURNT OUT. REQ:MARC DUSZA@5-4585 iNET	Routine Service Call	Closed	BU0614-200	TOWNSEND
10/9/2009	09-035723-000	POLYMER RESEARCH CENTER, LABORATORY 465B, FUMEHOOD EX-84-2 BRIEFLY GOES INTO ALARM WHENEVER THE FUME HOOD SASH IS MOVED. REQ: MARC DUSZA@5-4585 iNET	Routine Service Call	Closed	BU0614-100	TOWNSEND

Fume Hood Report

from 08/01/09 to 11/07/09

10/19/2009 09-036824-000	GOESSMANN, 162, PLEASE CHECK FUME HOODS. FH-0081-121, FH-0081-124, FH-0082-121, FH-0081-123. THANKS, TS REQ. TOM SPOONER, Phone: 413-387-9735 iNET	Routine Service Call	Closed	BU0081-100	LEE
10/22/2009 09-037051-000	CONTE : LABORATORY 465 FUME HOODS: IN CONTE LAB 465 FUME HOODS #613 AND #614 HAVE SEVERELY CHIPPED GLASS ON THE FUME HOOD SASHES. PLEASE REPLACE. REQ MARC DUZA 5-4585	Planned Work	Ready	BU0614-400	THIBAULT
10/23/2009 09-037078-000	MORRILL 4 N ROOMS N307 + N324 NEED FUMEHOODS RESET AFTER BUMP. R-608@9:30AM REQ.KELLY@5-1358 RITB036843	Routine Service Call	Closed	BU0347-100	HUSTED
10/23/2009 09-037130-000	GUNNESS, 15D, E AND F, PLEASE GIVE ESTIMATE TO DEMOLISH CABINETS IN GUNNESS 15E. PLEASE GIVE ESTIMATE TO DEMOLISH FUME HOOD IN GUNNESS 15E. PLEASE GIVE ESTIMATE TO PAINT WALLS AND FLOORS OF GUNNESS 15D, E AND F. CONTACT AL RAKOUSKAS (5-4541) AND/OR J. SUGLIA , JENNIFER SUGLIA, Phone: 545-3559, Fax: 545-1027	Planned Work	Progressing	BU0091-400	HAMELIN
10/26/2009 09-037189-000	FH0127-11 MORRILL 2, 426, THE FUME HOOD IN ROOM 426 IS STILL NOT WORKING PROPERLY. SOMETIMES THE FAN IS BLOWING, BUT SOMETIMES NOT. IT'S BEEN LOOKED AT SEVERAL TIMES ALREADY, BUT SOMETHING'S STILL NOT RIGHT. FOR DETAILS SEE MIKE KEEDY (5-3159) OR SALLY IVES (5-0449). REQ. SARA C. IVES, Phone: 5-0449 iNET	Routine Service Call	Ready	FH0127-11	LEE
11/5/2009 09-038652-000	MARCUS HALL ROOM 15A ALL THE FUME HOODS ARE GOING OFF PLEASE REPAIR R-608 @9.32 REQ.FRAN CARON 5-4578 RITB036796	Dispatch Service Call	Ready	BU0343-100	LEE
11/5/2009 09-038656-000	LGRT-A, 610, NO COLD WATER TO FUME HOOD. THANKS., REQ. MARVIN ELLIN, Phone: 545-3063 iNET	Routine Service Call	Closed	BU0412-300	HUSTED